

BUILDING SAFETY CERTIFICATE

Certified that the existing building **Chitrakoota Kaushalya School**, No. 10/5, Kengeri Ring Road, Nagadevanahalli, Bangalore - 560056 , Is having Block (s) Floor (s) as per details given below:

Details of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)
No. of Floors (s) in the Block	G+4				

The Building is owned/occupied by **Chitrakoota Kaushalya School** have complied with the Building Safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of **Karnataka Public Works Department** on **18-03-2026** in the presence of **The Administrator of Chitrakoota Kaushalya School** and that the building/ premises is fit for occupancy for running school for a period of **01** year in accordance with rule and subject to compliance of the specific conditions as appended.

1. The school should take necessary certificates from Fire department and other competent authorities within the time.
2. Building should be maintained neatly using good materials and experts.
3. The building should free from wall cracks, dampness, should take necessary action to fill cracks and avoid dampness in building. Patch plastering wherever necessary and periodically painting to be done.
4. The school should follow necessary safety precautions of students & teachers.
5. In the time of any changes in the structure of school building the school should take permission from competent authority. Otherwise, this certificate will get cancelled without any conditions.
6. The school should maintain neatly of drinking water facility, toilet neatness and other conditions from BBMP which are applied for schools and colleges.

Issued on: 24-03-2026 at Bangalore.

Signature with seal-----

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

Designation-----

Name & Address of Department/Office-----

ನಂ. 10/5 ಕೆಂಗೇರಿ ರಿಂಗ್ ರೋಡ್, ನಾಗದೇವನಹಳ್ಳಿ, ಬೆಂಗಳೂರು-560056

ಕೆ.ಪಿ.ವಿ.ಕೆ. ಅಂಚೆಪತ್ರ ವಿಭಾಗ, ಬೆಂಗಳೂರು-560 001

ಬೆಂಗಳೂರು-560 001